



HCI Suppliers Club Society

# JK TYRE & INDUSTRIES LIMITED



## UDGHOSH QUALITY CIRCLE WELCOMES YOU



Journey Towards Excellence....



1

Banmore Tyre Plant



HCI Suppliers Club Society



**J**uggilal Singhania



**K**amlapat Singhania

JK Organization owes its name to late Sri Lala **J**uggilal Singhania and his illustrious son late Sri Lala **K**amlapat Singhania, a dynamic personality with a broad vision.

Journey Towards Excellence....



2

Banmore Tyre Plant





## HISTORY OF JK TYRE INDS.



- Location-Kankroli  
• Founded-1977
- Location-Banmore  
• Founded-1991
- Location-Mysore  
• Acquired- 1996
- Location-Mexico  
• Acquired-2008
- Location- Chennai  
• Founded-2012
- Location- Haridwar  
• Acquired-2016

**9 plant in India at 5 Manufacturing locations**

**3 plant in Mexico**

Journey Towards Excellence....



3

Banmore Tyre Plant



## JK OEM CUSTOMERS



**HONDA**



**MARUTI SUZUKI**

Way of Life!



Journey Towards Excellence....



4

Banmore Tyre Plant





# JKTIL : Vision, Mission, Values House of JK Tyre

**Vision:** Be a Green and Trusted mobility partner

**Mission:**

- Be a customer centric company
- Deliver enhanced value to all stakeholders
- Be amongst Top 2 tyre brands in India with significant global presence
- Constantly innovate & provide technologically advanced solutions
- Achieve Process excellence by leveraging emerging technologies
- Be a learning organization with an engaged team
- Reduce carbon emission intensity to 50% by 2030



Journey Towards Excellence....



5

Banmore Tyre Plant



## INTRODUCTION OF UDGHOSH QUALITY CIRCLE

❖ Quality Circle Name	: UDGHOSH
❖ UDGHOSH QCC Foundation	: 2018
❖ Working Place	: TYRE UNIFORMITY
❖ Registration Number	: JKTIL/BTP/QC/20/2018
❖ Meeting day	: Saturday
❖ Date of Problem selection	: 30-12-2023
❖ Date of completion of trial Implementation	: 02-03-2024
❖ Date of Approval by the Management	: 03-03-2024
❖ Date of Project completion	: 06-04-2024

Journey Towards Excellence....








7

Banmore Tyre Plant





# TEAM DETAILS

-  **Mr. Anil Jha**      Facilitator
-  **Mr. Neeraj Saxena**      Leader
-  **Mr. Sushil Kumar**      Member
-  **Mr. Piyush Tiwari**      Member
-  **Mr. Sanjeev Gurjar**      Member

Journey Towards Excellence....



8

Banmore Tyre Plant



# TEAM ACHEIVEMENTS

NCQC-23 (Nagpur)



NCQC-24 (Gwalior)



Chairman trophy (JKO internal)



Journey Towards Excellence....



9

Banmore Tyre Plant







# Step-1

## IDENTIFICATION OF PROBLEMS



Tools/Techniques used:

- 1. Brainstorming

Journey Towards Excellence....



10

Banmore Tyre Plant



## Identification of Problem- Brainstorming Session



Journey Towards Excellence....



11

Banmore Tyre Plant





## Step-2

# SELECTION OF PROBLEM

Tools/Techniques used:

1. BrainStorming
2. Stratification
3. Pie Chart



Journey Towards Excellence....

Step 1 2 3 4 5 6 7 8 9 10 11 12

12

Banmore Tyre Plant



## STEP-2 : SELECTION OF PROBLEM

A , B & C Type problem Analysis

We have solved 10 problems of A-Type by KAIZEN during yr (2024)

# A

CAPABILITY

Problem to be solved with help of Circle members.

# B

CAPABILITY

Problem to be solved with help of other teams and departments.

# C

CAPABILITY


Problem to be solved by management approval and support

A Type = 35

B Type = 26

C Type = 07

**Total = 68**



Journey Towards Excellence....

Step 1 2 3 4 5 6 7 8 9 10 11 12

13

Banmore Tyre Plant





## STEP-2 : SELECTION OF PROBLEM

		<b>J K Tyre &amp; Industries Limited</b>		DATE: 02.01.2024	
Location: Tyre uniformity		Function: SSU2(QA)		Document No.: UTQM.005Q-66	
<b>Kaizen</b>				Area / Equipment: 9908	
Kaizen Title: To avoid tyre stuekup in Inlet conveyor				Kaizen No: 01	
<b>Problem:</b> During the tyres feeding from inlet conveyor to 9908 uniformity machine tyre stuekup in Inlet conveyor and flow of tyres disturb & machine output affected			<b>Solution through idea:</b> Railing provided in inlet conveyor for tyres feeding in center of feeding conveyor so that flow of tyres in even condition.		
Remarks: Benefit of fixing side railing in tyre feeding conveyor is that we can avoid Uniformity output loss and tyre stuekup					
Cost Impact (If Any)		Saving (If Any) : no		Standardization:	
Contributors: Mr. D.K.Tripathi , Mr. Rajendra Majhi					
Prepared By: Piyush Tiwari		Reviewed By: Abhinav Srivastava		Approval By: N.M.Roy	
Signature:		Signature:		Signature:	
				FORM NO-UTQM-00-005Q-13	

Journey Towards Excellence....

Step 1 2 3 4 5 6 7 8 9 10 11 12



14

Banmore Tyre Plant



## STEP-2 : SELECTION OF PROBLEM

Minimum Number implies Maximum Priority

We have got the problem of "Output target not met in Tyre Uniformity machine"

TEAM RATING					
"Minimum Number implies Maximum Priority"					
S.No.	PROBLEM	Sushil	Sanjeev	Piyush	Total
1	Marking not proper in solid shape	3	3	1	7
2	High Lube consumption	2	1	3	6
3	Output target not met in Tyre Uniformity machine	1	2	2	5
Selected Problem: "Output target not met in Tyre Uniformity machine "					

Journey Towards Excellence....

Step 1 2 3 4 5 6 7 8 9 10 11 12



15

Banmore Tyre Plant






# Step-3 DEFINITION OF THE PROBLEM



- Tools/Techniques used:
1. BRAINSTORMING
  2. MILESTONE CHART
  3. FLOW DIAGRAM

Journey Towards Excellence....



16

Banmore Tyre Plant



Step.No	Step Description	Milestone Chart														
		Week-->	06-01-2024	13-01-2024	20-01-2024	27-01-2024	03-02-2024	10-02-2024	17-02-2024	24-02-2024	02-03-2024	09-03-2024	16-03-2024	23-03-2024	30-03-2024	06-04-2024
3	Defining the Problem	Plan														
		Actual														
4	Analysis of problem	Plan														
		Actual														
5	Identification of causes	Plan														
		Actual														
6	Finding out of the root cause	Plan														
		Actual														
7	Data analysis of root cause	Plan														
		Actual														
8	Developing Solutions	Plan														
		Actual														
9	Foreseeing probable resistance	Plan														
		Actual														
10	Trial implementation & check performance	Plan														
		Actual														
11	Regular implementation	Plan														
		Actual														
12	Follow-up & Review	Plan														
		Actual														

Journey Towards Excellence....



17

Banmore Tyre Plant









## Definition of the Problem:

### What is Tyre Uniformity Test:

A tyre uniformity test is used to measure the consistency of a tyre's performance, It checks for variations in size, mass, and force that can affect ride quality and tyre life.

- **Radial Force Variation (RFV):** Measures changes in the force exerted by the tyre as it rotates
- **Lateral Force Variation (LFV):** Assesses side-to-side force changes
- **Conicity:** Evaluates the tyre's tendency to roll in a conical path
- **Run-out:** Measures deviations in the tyre's roundness
- **Balancing Test:** It ensure that the weight of the tyre and wheel assembly is evenly distributed to prevent vibrations and uneven wear.



These tests are conducted under controlled conditions, such as specific pressure, load, and speed, to ensure accurate results

Journey Towards Excellence....

Step 1 2 3 4 5 6 7 8 9 10 11 12

18

Banmore Tyre Plant



## Definition of the Problem:

### What is the Output of Tyre uniformity Machine:

Out put of TUO machine depends on following factors-

- 1- Feeding of tyre
- 2- lubing of tyre
- 3-The cycle time of tyre uniformity - it is time required to test the one tyre on the uniformity machine.
- 4 marking on tyre

### Specific Problem Statement:

“Output target not met in Tyre Uniformity machine ”



Journey Towards Excellence....

Step 1 2 3 4 5 6 7 8 9 10 11 12


19

Banmore Tyre Plant





# PROCESS FLOW DIAGRAM



Area under red box is our pain area with problem of "Output target not met in Tyre Uniformity Machine".

Journey Towards Excellence....



20

Banmore Tyre Plant



## Definition of the Problem:

### Impact of the Problem

- Loss of productivity
- TUO process Bottle neck
- Increases complexity
- Customer complaint
- Increases the waste



### Objectives

- Improve Productivity
- Improve delivery
- Complexity reduction
- Customer Satisfaction
- Reduce waste



Journey Towards Excellence....



21

Banmore Tyre Plant





# Definition of the Problem:



**Specific Problem Statement:**  
“Output target not met in Tyre Uniformity machine” Our target to achieve 90% output compliance.




## Step-4 ANALYSIS OF PROBLEM

Tools/Techniques used:  
1. 4 W+1 H  
2. Bar chart







# ANALYSIS OF THE PROBLEM




TUO Total OUTPUT



Shift wise target not met



Machine wise target not met



Size wise target not met

- Tyre uniformity total output compliance 74% from Oct.-Dec'23
- Shift wise target not met from Oct.-Dec'23
- TUO machine wise analysis revealed that ZF#2 & ZF#3 not meeting their output
- Size wise output not met in T135/70R15 STAR XT 38 times these machine

Journey Towards Excellence....



24

Banmore Tyre Plant



## Step-5

# IDENTIFICATION OF CAUSES

- Tools/Techniques used:
- 1.4M CONDITION
  - 2.GEMBA OBSERVATION
  - 3.BRAINSTORMING
  - 4.FISHBONE DIAGRAM



Journey Towards Excellence....



25

Banmore Tyre Plant







# IDENTIFICATION OF CAUSES

Gemba observation of team members



Possible causes through Brainstorming

Man	<ol style="list-style-type: none"> <li>1. Improper Feeding of tyre</li> <li>2. Flash trimming SOP not Followed</li> </ol>	Method	<ol style="list-style-type: none"> <li>1. The customer want only balance &amp; geometry measurement but we are doing all the measurements which are not required by customer</li> <li>2. Unable to run below 145mm width tyre</li> <li>3. Product mix</li> </ol>
Machine	<ol style="list-style-type: none"> <li>1. Machine is taking more cycle time for below 145 mm tread width tyre.</li> <li>2. No sufficient space to adjust the camera position</li> <li>3. Conveyor misalignment</li> <li>4. Tyre stuck to marking clamp</li> <li>5. Off-centre tyre mounting</li> <li>6. Only geometry &amp; Balancing measurement not possible</li> <li>7. Centering force variation</li> </ol>	Material	<ol style="list-style-type: none"> <li>1. Tyre stuck to lubrication due to more flexibility</li> <li>2. Wrong Barcode</li> <li>3. Barcode not readable</li> </ol>

Total 15 Possible causes were noted in brainstorming with the team Members

Journey Towards Excellence....




26


Banmore Tyre Plant



# IDENTIFICATION OF CAUSES



Journey Towards Excellence....



27

Banmore Tyre Plant





## Step-6

# Root causes & Validation of Root Causes

Tools/Techniques used:  
1. BRAINSTORMING



Journey Towards Excellence....

Step 1 2 3 4 5 6 7 8 9 10 11 12



28

Banmore Tyre Plant



## Finding out the Root causes

Sl.no	Main category	Possible Cause	Probable Root Cause
1	Man	Improper Feeding of tyre	Change of casual labours everyday
2		SOP not Followed	Non effectiveness of training
3	Machine	Machine is taking more cycle time	Two times geometry measurement
4		No sufficient space to adjust the camera position	Improper alignment of cable
5		Conveyor misalignment	No control for conveyor alignment
6		Tyre stuck to marking clamp	Clamp go below the bottom bead
7		Off-centre tyre mounting	Improper centering
8		Only geometry & Balancing measurement not possible	No option for single parameter check
9		Centering force variation	Inflation valve not working properly
10	Method	Product Mix	Non adequacy in SOP
11		The customer want only balance & geometry measurement but we are doing all the measurements which are not required by customer	Unable to disable uniformity measurement.
12		Complexity to run below 145mm width tyre	Issue in machine logic
13	Material	Tyre stuck to lubrication due to more flexibility	Due to flexibility centering arm push the tyre in one side
14		Wrong Barcode	Wrong measurement
15		Barcode not readable	Rubber flow on barcode

Journey Towards Excellence....

Step 1 2 3 4 5 6 7 8 9 10 11 12



29

Banmore Tyre Plant





## Finding out the Root causes

Sl.no	Main category	Possible Cause	Probable Root Cause	Validation method	Valid/Invalid
1	Man	Improper Feeding of tyre	Change of casual labors everyday	Operator skill matrix	Valid
2		SOP not Followed	Non effectiveness of training	Operator skill matrix	Invalid
3	Machine	Machine is taking more cycle time	Two times geometry measurement	MES	Valid
4		No sufficient space to adjust the camera position	Improper alignment of cable	Gemba visit	Valid
5		Conveyor misalignment	No control for conveyor alignment	Gemba visit	Valid
6		Tyre stuck to marking clamp	Clamp go below the bottom bead	Log & breakdown data	Valid
7		Off-centre tyre mounting	Improper centering	Log & breakdown data	Invalid
8		Only geometry & Balancing measurement not possible	No option for single parameter check	Simulation	Valid
9		Centering force variation	Inflation valve not working properly	Stimulation	Valid
10	Method	Product Mix	Same inch sizes running with higher OD	Stimulation	Valid
11		The customer want only balance & geometry measurement but we are doing all the measurements which are not required by customer	Unable to disable uniformity measurement.	Gemba visit	Valid
12		Complexity to run below 145mm width tyre	Issue in machine logic	MES	Valid
13	Material	Tyre stuck to lubrication due to more flexibility	Due to flexibility centering arm push the tyre in one side	Log & breakdown data	Invalid
14		Wrong Barcode	Wrong measurement	Simulation	Invalid
15		Barcode not readable	Rubber flow on barcode	Tyre get bypassed by machine	Invalid

Journey Towards Excellence....



30

Banmore Tyre Plant



Step 1 2 3 4 5 6 7 8 9 10 11 12



## Finding out the Root causes

After fish bone analysis we have 15 probable root causes, but after validation we have 10 root cause, which is shown below.

Sr. No	Root Cause
1	Change of casual labors everyday
2	Two times geometry measurement
3	Improper alignment of cable
4	No control for conveyor alignment
5	Clamp go below the bottom bead
6	No option for single parameter check
7	Unable to disable uniformity measurement.
8	Non adequacy in SOP
9	Inflation valve not working properly
10	Issue in machine logic

Journey Towards Excellence....



31

Banmore Tyre Plant



Step 1 2 3 4 5 6 7 8 9 10 11 12



# Step-7

## DATA ANALYSIS

Tools/Techniques used:  
1. PARETO ANALYSIS



Journey Towards Excellence....

Step 1 2 3 4 5 6 7 8 9 10 11 12

32


Banmore Tyre Plant



## DATA ANALYSIS

We have prioritized the root cause for given the priority of impact the problem.

S.No.	Root Cause	Percentage productivity loss	Cum. (%)
1	Two times geometry measurement	40	40
2	No control for conveyor alignment	15	55
3	Unable to disable uniformity measurement.	12	67
4	Improper alignment of cable	11	78
5	Issue in machine logic	5	83
6	Change of casual labors everyday	5	88
7	Clamp go below the bottom bead	4	92
8	No option for single parameter check	3	95
9	Non adequacy in SOP	3	98
10	Inflation valve not working properly	2	100
Total		100	



Journey Towards Excellence....

Step 1 2 3 4 5 6 7 8 9 10 11 12

33

Banmore Tyre Plant







# Step-8

## DEVELOPING SOLUTIONS



Tools/Techniques used:  
 1. BRAINSTORMING  
 2. GEMBA

Journey Towards Excellence....



34

Banmore Tyre Plant



Step 1 2 3 4 5 6 7 8 9 10 11 12



## DEVELOPING SOLUTIONS

Root Causes	Developing Solutions	Status	Remark
Two times geometry measurement	Modify the marking clamp as per the requirement.	Rejected	Modified clamp will not suitable for higher inch sizes
	Set tread width height more than actual	Accepted	We can set tread width height in machine program easily.
No control for conveyor alignment	Fix sensor for auto control	Rejected	It's cost very high.
	Implement the visual control for conveyor adjustment.	Accepted	We can made easily In-house.
Unable to disable uniformity measurement.	Install separate machine for one parameter checking	Rejected	It's cost very high.
	Modify the logic so specifically any one of the parameter can be run	Accepted	With OE support we can modify logic
Improper alignment of cable	Take separate geometry measurement for top & bottom side..	Rejected	We can align cable and sensor with the help mech.
	Align the cables & sensor which are comes across the geometry assemble moment.	Accepted	It will increase the cycle time by 10-12 sec.

Journey Towards Excellence....



35

Banmore Tyre Plant



Step 1 2 3 4 5 6 7 8 9 10 11 12



# DEVELOPING SOLUTIONS

S.No.	Root Causes	Developing Solutions	Responsibility	By Whom	Target Date
1	Two times geometry measurement	Set tread width height more than actual	Piyush Tiwari	Instrumentation	25-02-2024
2	No control for conveyor alignment	Implement the visual control for conveyor adjustment.	Neeraj Saxena	Mechanical	28-02-2024
3	Unable to disable uniformity measurement.	Modify the logic so specifically any one of the parameter can be run	Sanjeev Gurjar	Instrumentation	29-02-2024
4	Improper alignment of cable	Align the cables & sensor which are comes across the geometry assemble moment	Sushil Kumar	Mechanical	25-02-2024

Journey Towards Excellence....



36

Banmore Tyre Plant



Step 1 2 3 4 5 6 7 8 9 10 11 12



## Step-9

# FORESEEING PROBABLE RESISTANCE



Tools/Techniques used:  
1. BRAINSTORMING

Journey Towards Excellence....



37

Banmore Tyre Plant



Step 1 2 3 4 5 6 7 8 9 10 11 12



# FORESEEING PROBABLE RESISTANCE

S.No.	Solutions	Resistance	Idea
1	Set tread width height more than actual	How much tread width height should be increase ?	We discussed with our engineering team and after trial decided 15-20 mm tread width height more than actual .
2	Implement the visual control for conveyor adjustment.	What type of control should to installed ?	We discussed with our engineering team and decided metallic scale fix conveyor adjustment.
3	Modify the logic so specifically any one of the parameter can be run	Single process to check both bulge and runout parameter and system control by OE?	We discussed with our team and decided Modify the program and logic .
4	Align the cables & sensor which are comes across the geometry assemble moment	Cable length short ?	We discussed with our engineering team cable change with increase length.

Journey Towards Excellence....  38 Banmore Tyre Plant 

Step 1 2 3 4 5 6 7 8 9 10 11 12



## Step-10

# TRIAL IMPLEMENTATION & CHECK PERFORMANCE



Tools/Techniques used:  
 1.DATA COLLECTION  
 2.LINE GRAPH


Journey Towards Excellence....  39 Banmore Tyre Plant 

Step 1 2 3 4 5 6 7 8 9 10 11 12



# TRIAL IMPLEMENTATION & CHECK PERFORMANCE

## PDCA CYCLE



Journey Towards Excellence.... 40 Banmore Tyre Plant

Step 1 2 3 4 5 6 7 8 9 10 11 12



# TRIAL IMPLEMENTATION & CHECK PERFORMANCE

BEFORE	AFTER
<p><b>CAUSE:</b> No visual control for adjust the conveyor width according to the rim size.</p>	<p><b>Solution:</b> Implemented visual control to adjust the conveyor width according to the rim size.</p>

Journey Towards Excellence.... 41 Banmore Tyre Plant

Step 1 2 3 4 5 6 7 8 9 10 11 12





## TRIAL IMPLEMENTATION & CHECK PERFORMANCE

**BEFORE**

**AFTER**



**CAUSE:**

The tyre is very flexible & it is frequently getting stuck in to the conveyor so the speed of conveyor reduced to 50%.

**Solution:**

Adjust the conveyer width & run with 100% speed

Journey Towards Excellence....



42


Banmore Tyre Plant



## TRIAL IMPLEMENTATION & CHECK PERFORMANCE

**BEFORE**

**AFTER**



Tire Size	T135/70R15_STAR XT_99M TL
Tire Width	135.00 mm
Rim Width	4.5 "
Cony Correction	0.00 kgf
<input type="checkbox"/> Critical Tire	

Tire Size	T135/70R15_STAR XT_99M TL
Tire Width	162.00 mm
Rim Width	4.5 "
Cony Correction	0.00 kgf
<input type="checkbox"/> Critical Tire	

**CAUSE:**

Below 145 mm of tread width marking clamp goes below bottom bead.

**Solution:**

Set the tread width 162 mm at M- Conf program

Journey Towards Excellence....



43

Banmore Tyre Plant





## TRIAL IMPLEMENTATION & CHECK PERFORMANCE

BEFORE	AFTER
<p><b>CAUSE:</b></p> <p>No sufficient space to camera forward position</p>	<p><b>Solution:</b></p> <p>All cables are fixed below the geometry assembly.</p>

Journey Towards Excellence....

Step 1 2 3 4 5 6 7 8 9 10 11 12



44

Banmore Tyre Plant



## TRIAL IMPLEMENTATION & CHECK PERFORMANCE

BEFORE	AFTER
<p><b>CAUSE:</b></p> <p>Logic in to the system is not testing the single parameter during uniformity testing</p>	<p><b>Solution:</b></p> <p>Modify the program so specifically any one of the parameter can be run.</p>

Journey Towards Excellence....



45


Banmore Tyre Plant





# TRIAL IMPLEMENTATION & CHECK PERFORMANCE

Firstly we have been taken trial on ZF#2 machine and after trial implementation We have collected cycle time data





Journey Towards Excellence... **46** Banmore Tyre Plant



# TRIAL IMPLEMENTATION & CHECK PERFORMANCE

**BEFORE**

**AFTER**



Journey Towards Excellence... **47** Banmore Tyre Plant



# Step-11

## REGULAR IMPLEMENTATION

Tools/Techniques used:

1. DATA COLLECTION
2. LINE GRAPH



Journey Towards Excellence....



48

Banmore Tyre Plant



## REGULAR IMPLEMENTATION

- We have discussed with our Seniors, HOD about the suggestions. They appreciated the suggestions and given permission to continue the work.
- We have discussed with engineering department, they also appreciate the work and told to maintain it in future.
- We have Solutions horizontal deployed at TUO machine ZF#2 & 3.



Journey Towards Excellence....



49

Banmore Tyre Plant





# REGULAR IMPLEMENTATION

S.No.	Root Causes	Developing Solutions	Responsibility	By Whom	Target Date
1	Two times geometry measurement	Set tread width height more than actual	Piyush Tiwari	Instrumentation	09-03-2024
2	No control for conveyor alignment	Implement the visual control for conveyor adjustment.	Neeraj Saxena	Mechanical	10-03-2024
3	Unable to disable uniformity measurement.	Modify the logic so specifically any one of the parameter can be run	Sanjeev Gurjar	Instrumentation	11-03-2024
4	Improper alignment of cable	Align the cables & sensor which are comes across the geometry assemble moment	Sushil Kumar	Mechanical	11-03-2024

Journey Towards Excellence....




50

Banmore Tyre Plant



# REGULAR IMPLEMENTATION



Journey Towards Excellence....



51

Banmore Tyre Plant









**REGULAR IMPLEMENTATION**

**Appreciation Letter**

Appreciation letter from GM ( Commercial)



Journey Towards Excellence....



54

Banmore Tyre Plant



**REGULAR IMPLEMENTATION**

**INTANGIBLE BENEFITS**

- **Increased employee morale**
- **Complexity Reduction**
- **Customer satisfaction**
- **Reduce waste (waiting time)**
- **Knowledge increased**



**HONDA**

Honda Cars India Ltd.  
Plot No. A-1, Sector 49/41, Surajpur-Kanina Road,  
Greater Noida Industrial Development Area,  
Dist. Gautam Buddha Nagar (U.P.) Ph : 201306  
Tel. : +91-120-2341213 / 2011 / 2071 801 / 806  
Fax : +91-120-2341261

S/07  
M/S. JK TYRE & INDUSTRIES LIMITED  
C-1 INDUSTRIAL AREA,  
M BANMORRE,  
DISTT MORERHA,  
MADHYA PRADESH

Dated:- 16-Jan-25

KIND ATTN : Mr. Srinivasu Atlaphan (Director-Sales & Marketing)

**Sub: Delivery & Quality Data for Dec'24**

Dear Sir,

We appreciate your services to HCL.

Kindly note the Quality & Delivery performance of your company vis-à-vis our targets :

DELIVERY			QUALITY			MARKET FAILURE	
No. of Problems	GDI Score	RANK	No. of Problems	GQI Score	RANK	Market Failures	Date
(Based on No of problems reported)	(Based on weightage of defects)	Rank / Out of	(Based on No of problems reported)	(Based on weightage of defects)	Rank / Out of	No. of Claim's	No. of Part's
0	0	1 / 200	0	0	1 / 200	0	0

Journey Towards Excellence....



55

Banmore Tyre Plant





# Step-12 FOLLOW-UP & REVIEW

Tools/Techniques used:  
1. DATA COLLECTION

Journey Towards Excellence....

Step 1 2 3 4 5 6 7 8 9 10 11 12

56

Banmore Tyre Plant



# FOLLOW-UP & REVIEW

Lubrication schedule to ensure timely lubrication

ZF Lubrication Schedule- JAN-24 to MAR. 24							
Sr.No.	Date	Grease Qun	Filled By	Sign	Verified By	Sign	Remark
1	23-01-2024	05 NOS	Mech	<i>[Signature]</i>			
2	31-01-2024	07 NOS	Mech	<i>[Signature]</i>	<i>[Signature]</i>		
3	07-02-2024	06 NOS	Mech	<i>[Signature]</i>	<i>[Signature]</i>		
4	14-02-2024	05 NOS	Mech	<i>[Signature]</i>	<i>[Signature]</i>		
5	21-02-2024	07 NOS	Mech	<i>[Signature]</i>	<i>[Signature]</i>		
6	28-02-2024	06 NOS	Mech	<i>[Signature]</i>	<i>[Signature]</i>		
7	06-03-2024	04 NOS	Mech	<i>[Signature]</i>	<i>[Signature]</i>		
8	13-03-2024	05 NOS	Mech	<i>[Signature]</i>	<i>[Signature]</i>		
9	20-03-2024	03 NOS	Mech	<i>[Signature]</i>	<i>[Signature]</i>		
10	28-03-2024	7 NOS	Mech	<i>[Signature]</i>	<i>[Signature]</i>		
11	03-04-2024	04 NOS	Mech	<i>[Signature]</i>	<i>[Signature]</i>		
12	10-04-2024 11-04-2024	05 NOS	Mech	<i>[Signature]</i>	<i>[Signature]</i>		

Journey Towards Excellence....

Step 1 2 3 4 5 6 7 8 9 10 11 12

57

Banmore Tyre Plant





Star XT running instruction has been monitored in DWM

Daily Work Management consolidate sheet - March 24

Sl.No	MP/CP No	Parameter	Primary Person	Secondary Person	Graph	Target	Average	Daily															
								1	2	3	4	5	6	7	8	9	10	11	12	13	14		
1	5.1.1	Safety	All		OPEN	0	0.0667	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	1
5		Less than 90 % Sizes- TUO	Saleem	Datta		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
16		TUO Tyre damage	Saleem	Datta	OPEN	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
17		Star XT at TUO (Should run in batch)	Saleem	Datta		#DIV/0!	NA	NA	NA	YES	YES	YES	YES	YES	YES	YES	YES	YES	YES	YES	YES	YES	YES
18		TUO Left over	Saleem	Datta	OPEN	100	1073.8	375	610	770	700	1350	863	1350	1400	1350	1178	1400	980	1050	2500		

MachineName	Press Name	Mould Name	Barcode	Sapcode	Tyre Type	Date	Shift	CycleTime	UniformityGrade	Lo
ZF-1	4922	B13570R15STRXTSX01	1036438966	1325213615099MSX0T	T13570SSTXT99MTL	06-03-2024 06:59:16	C	23.7	A	0
ZF-1	4922	B13570R15STRXTSX01	1036438544	1325213615099MSX0T	T13570SSTXT99MTL	06-03-2024 05:54:07	C	22.7	A	0
ZF-1	4923	B13570R15STRXTSX03	1036438634	1325213615099MSX0T	T13570SSTXT99MTL	06-03-2024 05:53:44	C	22.85	A	0
ZF-1	4915	B13570R15STRXTHM01	1036438783	1325213615099MSX0T	T13570SSTXT99MTL	06-03-2024 05:53:21	C	24.65	A	0
ZF-1	4922	B13570R15STRXTHM03	1036437962	1325213615099MSX0T	T13570SSTXT99MTL	06-03-2024 05:52:59	C	21.96	A	0
ZF-1	4922	B13570R15STRXTHM03	1036461434	1325213615099MSX0T	T13570SSTXT99MTL	06-03-2024 05:52:35	C	25.17	A	0
ZF-1	4922	B13570R15STRXTHM03	1036438207	1325213615099MSX0T	T13570SSTXT99MTL	06-03-2024 05:52:09	C	22.73	A	0
ZF-1	4922	B13570R15STRXTHM03	1036438556	1325213615099MSX0T	T13570SSTXT99MTL	06-03-2024 05:51:47	C	25.69	A	0

Digital MS TUO Report

Journey Towards Excellence...

Step	1	2	3	4	5	6	7	8	9	10	11	12
------	---	---	---	---	---	---	---	---	---	----	----	----

58

Banmore Tyre Plant



# FOLLOW-UP & REVIEW

Training Attendance Record (for Class Room Training) SSU4.01-FR.02A

Programme Title :- NEW set-up of 9-Stroke tyre.

Date From :- 13/03/24 To :- 22/03/24

Time: To:

Venue :- OT Job Training

Faculty :- Mr. A. A. A., Mr. Himanshu, Mr. Raj, Mr. Rashmi

Programme Coordinator :-

S.No	Sap Code	Name	Designation	Dept/Location	Signature
1	78791	Akash Tripathi	DAI	SSU4.01	[Signature]
2	78792	Srinivas Chandra	DAI	SSU4.01	[Signature]
3	26304	Manoj Kumar	DET	SSU4.01	[Signature]
4	26314	Anon Dhanu	DET	SSU4.01	[Signature]
5	26212	Akash Saha	DET	SSU4.01	[Signature]
6	26038	HIMANSHU RANTAN	DET	SSU4.01	[Signature]
7	78801	Chiranjeev Singh	DAI	SSU4.01	[Signature]
8	26970	Chiranjeev Singh	DAI	SSU4.01	[Signature]
9	78822	Srinivas Chandra	DAI	SSU4.01	[Signature]
10	26947	Ratan Kumar	DET	SSU4.01	[Signature]
11	26908	Ratan Kumar	DET	SSU4.01	[Signature]
12	26901	Ram Babu Sharma	DET	SSU4.01	[Signature]
13	26174	Pranav Dhanu	DET	SSU4.01	[Signature]
14	24107	Ravi	DET	SSU4.01	[Signature]
15	78792	Srinivas Chandra	DAI	SSU4.01	[Signature]
16	26211	Ravi Kumar	DET	SSU4.01	[Signature]
17	26592	Chiranjeev Singh	DET	SSU4.01	[Signature]
18	26585	Chiranjeev Singh	DET	SSU4.01	[Signature]
19	26514	Chiranjeev Singh	DET	SSU4.01	[Signature]
20	78812	Anon Kishan	DAI	SSU4.01	[Signature]

All the inspectors & Operators have been communicated regarding the modification/Changes in 135/70R15 STAR XT TL size set up.

Journey Towards Excellence...

Step	1	2	3	4	5	6	7	8	9	10	11	12
------	---	---	---	---	---	---	---	---	---	----	----	----

59

Banmore Tyre Plant



Step.No.	Step Description	QUALITY CIRCLE NAME :- UDGHOSH Project Title: Output target not met in Tyre Uniformity machine Project Start : 30.12.2023 Project Completed : 06.04.2024														
		Regn no.:JKTIL/BTP/QC/20/2018 Department : SSU#2 QA Project Category: A														
		Week->	06-01-2024	13-01-2024	20-01-2024	27-01-2024	03-02-2024	10-02-2024	17-02-2024	24-02-2024	02-03-2024	09-03-2024	16-03-2024	23-03-2024	30-03-2024	06-04-2024
3	Defining the Problem	Plan	█													
		Actual	█													
4	Analysis of problem	Plan		█												
		Actual		█												
5	Identification of causes	Plan			█											
		Actual			█											
6	Finding out of the root cause	Plan				█										
		Actual				█										
7	Data analysis of root cause	Plan					█									
		Actual					█									
8	Developing Solutions	Plan						█								
		Actual						█								
9	Foreseeing probable resistance	Plan							█							
		Actual							█							
10	Trial implementation & check performance	Plan								█	█					
		Actual								█	█					
11	Regular implementation	Plan										█	█	█		
		Actual										█	█	█		
12	Follow-up & Review	Plan													█	█
		Actual													█	█

### Milestone Chart

Journey Towards Excellence....




60

Banmore Tyre Plant



## FOLLOW-UP & REVIEW



Journey Towards Excellence....



61




Banmore Tyre Plant





**TOOLS & TECHNIQUES USED IN THIS PROJECT**

- **CAUSE & EFFECT DIAGRAM**
- **BAR GRAPH**
- **DATA COLLECTION**
- **PDCA CYCLE**
- **PARETO DIAGRAM**
- **STRATIFICATION**
- **BRAIN STROMING**
- **4W + 1H**



**QC Challenges**

**Quality**

- Poor dot marking
- Improper id line
- High bay rejection

**Productivity**

- High breakdown
- High MTTR & Low MTBF

**Cost**

- Rework
- High consumption of lube & marking tape





Next Project

Reduction Lube consumption by 30%.



Journey Towards Excellence

- Step 1
- 2
- 3
- 4
- 5
- 6
- 7
- 8
- 9
- 10
- 11
- 12

64

Banmore Tyre Plant



*Thank You*

Question and Suggestion please

Journey Towards Excellence....



65

Banmore Tyre Plant

